Proposed Subdivision
Billy's Lookout - Stage 15
Site Classification

Fishermans Drive, Teralba

NEW15P-0070B-AK 29 April 2020



29 April 2020

McCloy Development Management Pty Ltd Suite 2, Ground Floor, 317 Hunter Street NEWCASTLE NSW 2300

**Attention: Harry Thomson** 

Dear Sir

RE: PROPOSED SUBDIVISION – BILLY'S LOOKOUT - STAGE 15 FISHERMANS DRIVE, TERALBA SITE CLASSIFICATION (LOTS 1501 TO 1530)

Please find enclosed our geotechnical report for Stage 15 of the proposed residential subdivision of Billy's Lookout, located at Fishermans Drive, Teralba.

The report provides site classification with respect to reactive soils, in accordance with the requirements of AS2870-2011 'Residential Slabs and Footings', for Stage 15 (Lots 1501 to 1530), following the completion of site regrading works.

If you have any questions regarding this report, please do not hesitate to contact Ben Bunting, Shannon Kelly, or the undersigned.

For and on behalf of Qualtest Laboratory (NSW) Pty Ltd

Jason Lee

Principal Geotechnical Engineer

## **Table of Contents:**

1.0		Introduction	
2.0		Desktop Study	
3.0		Field Work	1
4.0		Site Description	2
	4.1	Site Regrade Works	2
	4.2	Surface Conditions	2
	4.3	Subsurface Conditions	5
5.0		Laboratory Testing	9
6.0		Site Classification to AS2870-2011	10
7.0		Limitations	11

i

### **Attachments:**

Figure AK1: Site Plan and Approximate Test Locations

Appendix A: Results of Field Investigations
Appendix B: Results of Laboratory Testing

Appendix C: CSIRO Sheet BTF 18

#### 1.0 Introduction

Qualtest Laboratory NSW Pty Ltd (Qualtest) is pleased to present this geotechnical assessment report on behalf of McCloy Development Management Pty Ltd (McCloy), for Stage 15 of the residential subdivision of Billy's Lookout, located at Fishermans Drive, Teralba.

Based on Construction Certificate drawings including the Retaining Wall Plan provided, (Ref. Drawing Nos. CO13231.01-DA15-60, Issue B, dated 22 February 2019, by Costin Roe Consulting Pty Ltd), Stage 15 is understood to comprise 30 residential lots (Lots 1501 to 1530), as shown on Figure AK1.

The scope of work for the geotechnical investigation included providing site classification with respect to reactive soils, in accordance with the requirements of AS2870-2011 'Residential Slabs and Footings', for Stage 15 following the completion of site regrading works.

This report presents the results of the field work investigations and laboratory testing, and provides recommendations for the scope outlined above.

### 2.0 Desktop Study

The scope of work has included a review of the following reports completed by Qualtest:

- Level 1 Site Regrade Assessment report, 'Proposed Subdivision, Billy's Lookout Stage 15,
   Fishermans Drive, Teralba, (Report Reference: NEW19P-0042A-AA, dated 8 April 2020); and,
- Geotechnical Assessment report, 'Proposed Subdivision, Billy's Lookout Stages 13, 14 & 15
  Fishermans Drive, Teralba, (Report Reference: NEW15P-0070B-AB.Rev1, dated 26 June
  2017).

This report includes a summary of selected results from the previous reports where applicable.

#### 3.0 Field Work

Field work investigations were carried out on 7 April 2020 and comprised of:

- DBYD search of proposed test locations was undertaken to check proposed test locations for the presence of underground services;
- Site walkover to make observations of surface features at the property and in the immediate surrounding area;
- Excavation of 15 test pits (TP1501 to TP1515) using a 2.7 tonne rubber tracked excavator equipped with a 0.45m wide toothed bucket, to depths of between 0.60m to 2.15m;
- Undisturbed samples (U50 tubes) were taken for subsequent laboratory testing; and,
- Test pits were backfilled with the excavation spoil and compacted using the excavator bucket and tracks.

Investigations were carried out by an experienced Geotechnical Engineer from Qualtest who located the test pits, carried out the testing and sampling, produced field logs of the test pits, and made observations of the site surface conditions.

Engineering logs of the test pits are presented in Appendix A.

Approximate test pit locations are shown on the attached Figure AK1. Test pits were located in the field with reference to site features including lot boundaries, retaining walls, and constructed pavements.

### 4.0 Site Description

#### 4.1 Site Regrade Works

Following an initial site visit, stripping assessment and recommendations performed on 7 November 2019 (Qualtest ref. NEW19P-0042A-SR01, dated 11/11/19), site re-grading works were conducted between 7 November 2019 and 11 March 2020.

The re-grading works consisted of the cutting and filling of proposed residential lots within Stage 15 of the subdivision (Lots 1501 to 1530).

Prior to filling, re-grade areas were stripped of all topsoil and unsuitable material to expose suitable natural foundation profile. Re-grade works then consisted of filling with approved site fill to finish design levels.

Filling was performed using site material won from excavations cut from around the site. The fill material could generally be described as mixtures of Gravelly Sandy CLAY, of low to medium plasticity, fine to coarse grained sand, with some fine to coarse grained gravel inclusions.

The approximate depth of fill placed ranged in the order of 0.1m to about 2.0m. The fill was compacted in maximum lifts of 0.3m thickness. Any unsuitable or deleterious material within the fill was removed by hand or mechanical means prior to final compaction of the material.

As the geotechnical testing authority engaged for the project, Qualtest state that the filling performed for the regrade areas (Lots 1501 to 1530), was carried out to Level 1 criteria as defined in Clause 8.2 – Section 8, of AS3798-2007, 'Guidelines on Earthworks for Commercial and Residential Developments'. Refer to site regrade letters referenced in Section 2.0 for further details

At the time of the field investigations on 7 April 2020, some fill stockpiles (mostly mulch and topsoil) were still present on a number of lots. It is understood and expected that the stockpiles will be removed prior to development on the lots.

The recommendations of this report are based on the understanding that any existing lot re-grade works are limited to the controlled earthworks works supervised by Qualtest, and placement of low reactivity topsoil material such that total topsoil depths do not exceed 0.4m. Qualtest should be informed without delay if additional earthworks are known to have been carried out.

#### 4.2 Surface Conditions

The site comprises Stage 15 of the residential subdivision known as Billy's Lookout, located off Fishermans Drive, Teralba, as shown on Figure AK1 attached.

The site is bounded to the east by Stage 14 of the Billy's Lookout residential subdivision, by undeveloped bushland to the north, a disused railway corridor to the west, and by proposed Stage 23 and the Main Northern Railway to the south.

The site is located within a region of gently to moderately undulating topography, on the south to southwest facing mid slopes of a prominent hill formation which rises to the north of the site. Site slopes generally vary from about 2° to 5° over the majority of the site, with some locally steeper batters of up to around 30°. Earthworks on the site have approximately levelled the residential lots, with construction of several retaining walls of up to about 1.40m height.

Ground levels range from about RL 53m (AHD) at the northern part of the site, to about RL 34m (AHD) towards the southern boundary of the site.

The site generally comprises vacant lots, with some blockwork retaining walls located approximately on site boundaries to achieve levels. Lots are unvegetated, and most are covered with a roughly 50mm layer of top mulch.

On the day of the investigation which was carried out after a period of wet weather, the majority of the site was judged to be drained primarily by way of surface runoff following the natural and altered topography towards gullies and the southern boundary of the site. The stormwater drainage system was partially installed at the time of site investigation, and the topsoil material was observed to be boggy in multiple areas.

Trafficability was judged to be good by way of 4WD vehicle.

Photographs of the site taken on the day of the site investigations are shown below.



**Photograph 1:** From north-eastern boundary of Lot 1501, facing southwest.



**Photograph 2:** From north-eastern boundary of Lot 1501, facing west.



**Photograph 3:** From northern end of Lot 1503, facing south.



**Photograph 4:** From northern end of Lot 1503, facing west.



**Photograph 5:** From near southern end of Lot 1506, facing southwest.



**Photograph 6:** From near southern end of Lot 1506, facing west.



**Photograph 7:** From near southern end of Lot 1506, facing northwest.



**Photograph 8:** From near southern end of Lot 1506, facing north.



**Photograph 9:** From near southern boundary of Lot 1509, facing east.



**Photograph 10:** From near southern boundary of Lot 1509, facing southeast.



**Photograph 11:** From southern boundary of Lot 1511, facing southeast.



**Photograph 12:** From southern boundary of Lot 1511, facing southwest.



**Photograph 13:** From Road 16 near Lots 1517 and 1524, facing north.



**Photograph 14:** From Road 16 near Lots 1517 and 1524, facing northeast.



**Photograph 15:** From northern end of shared boundary of Lots 1526 and 1527, facing southwest.



**Photograph 16:** From northern end of shared boundary of Lots 1526 and 1527, facing west.



**Photograph 17:** From southern corner of Lot 1527, facing north.



**Photograph 18:** From southern corner of Lot 1527, facing northeast.



**Photograph 19:** From north-eastern corner of Lot 1529, facing west.



**Photograph 20:** From north-eastern corner of Lot 1529, facing northwest.

#### 4.3 Subsurface Conditions

Reference to the 1:100,000 Newcastle Coalfield Regional Geology Sheet indicates the site to be underlain by the Clifton Subgroup of the Narrabeen Group, which are characterised by Conglomerate, Sandstone, Siltstone and Claystone rock types.

Table 1 presents a summary of the typical soil types encountered at test pit locations during the field investigation, divided into representative geotechnical units.

Table 2 contains a summary of the distribution of the above geotechnical units at the test pit locations.

TABLE 1 – SUMMARY OF GEOTECHNICAL UNITS AND SOIL TYPES

Unit	Soil Type	Description					
		Mulch in places to depths of about 0.05m to 0.2m, overlying;					
	FILL – TOPSOIL &	Sandy CLAY – low plasticity, grey-brown, fine to medium grained sand, with some mulch.					
1A	MULCH	Clayey SAND / Sandy CLAY – fine to coarse grained, greybrown to pale grey-brown, fines of low plasticity, with some fine to medium grained angular to sub-angular gravel, with some mulch.					
18	FILL - CONTROLLED	Gravelly Sandy CLAY – low to medium plasticity, pale orange- brown and brown to grey-brown, fine to coarse grained (mostly fine to medium grained) sand, fine to coarse grained angular to sub-angular gravel, trace cobbles.					
		Sandy CLAY – medium plasticity, pale red-brown to orange- brown, fine to coarse grained sand.					
2	TOPSOIL	Not Encountered.					
3	SLOPEWASH /	Sandy CLAY – low to medium plasticity, dark grey-brown, fine to medium grained sand.					
3	COLLUVIUM  Clayey SAND – fine to medium grained, dark brown to a grey-brown, fines of low plasticity.						
4	residual soil	Sandy CLAY – medium to high plasticity, grey to pale orange- brown / red-brown to orange-brown / red-brown and pale grey to white, fine to medium grained sand, with some roots in places.					
5	EXTREMELY WEATHERED (XW) ROCK with soil	Sandstone; breaks down into Gravelly Sandy CLAY / Sandy CLAY – medium plasticity, orange-brown and pale grey, fine to coarse grained (mostly fine to medium grained) sand, fine to medium grained angular gravel.					
	properties	Sandy Siltstone; breaks down into Sandy CLAY – medium to high plasticity, pale orange-brown with some pale grey, fine to medium grained sand.					
	HIGHLY	Silty SANDSTONE – fine grained, orange-brown to pale grey, estimated very low to low strength.					
6	WEATHERED (HW) ROCK	SANDSTONE – fine to medium grained, orange-brown to redbrown with some pale grey to white, estimated very low to low strength.					

TABLE 2 – SUMMARY OF GEOTECHNICAL UNITS ENCOUNTERED AT EACH TEST PIT LOCATION

Location	Unit 1A Fill – Topsoil & Mulch	Unit 1B Fill - Controlled	Unit 2 Topsoil	Unit 3 Slopewash / Colluvium	Unit 4 Residual Soil	Unit 5 XW Rock	Unit 6 HW Rock
	Molen			Depth in metres (m	<u> </u> )		
		Cui	rent Investigation	– After Site Regrade	• Works		
TP1501	0.00 - 0.30	0.30 - 2.00	-	-	-	-	-
TP1502	0.00 - 0.25	0.25 - 1.80	-	-	1.80 - 2.00	-	-
TP1503	0.00 - 0.30	0.30 - 1.00	-	-	1.00 - 1.80^	-	-
TP1504	0.00 - 0.20	0.20 - 1.60	-	-	1.60 - 2.00	2.00 - 2.15	-
TP1505	0.00 - 0.15	0.15 - 1.40	-	-	1.40 - 2.00	-	-
TP1506	0.00 - 0.20	0.20 - 0.60	-	0.60 - 0.70	0.70 - 2.00	-	-
TP1507	0.00 - 0.10	0.10 - 0.90	-	0.90 - 1.10	1.10 - 2.00	-	-
TP1508	0.00 - 0.20	0.20 - 0.50	-	0.50 - 0.60	0.60 - 1.55	-	1.55 - 1.60^
TP1509	0.00 - 0.30	-	-	-	0.30 - 0.50	0.50 - 0.60	0.60 - 0.65*
TP1510	0.00 - 0.30	0.30 - 0.55	-	-	0.55 - 1.10	1.10 - 1.50	1.50 - 1.60*
TP1511	-	0.00 - 0.15	-	-	0.15 - 0.20	0.20 - 0.50	0.50 - 0.60*
TP1512	-	0.00 - 2.00	-	-	-	-	-
TP1513	0.00 - 0.20	0.20 - 0.40	-	-	0.40 - 1.70	1.70 - 1.80^	-
TP1514	0.00 - 0.05	0.05 - 0.75	-	-	0.75 - 1.95	1.95 - 2.05	-
TP1515	0.00 - 0.30	0.30 - 1.80	-	-	1.80 - 2.05	-	-

	Unit 1A	Unit 1B	Unit 2	Unit 3	Unit 4	Unit 5	Unit 6
Location	Fill – Topsoil & Mulch	Fill - Controlled	Topsoil	Slopewash / Colluvium	Residual Soil	XW Rock	HW Rock
				Depth in metres (m	)		
	Previous	Investigation (NEW	15P-0070B-AB.Rev1	, dated 26 June 20	17) – Prior to Site Re	grade Works	
TP301	-	-	0.00 – 0.15	0.15 - 0.40	-	-	0.40 - 0.70*
TP302	-	-	0.00 - 0.12	0.12 - 0.20	0.20 - 0.60	0.60 - 1.40^	-
TP303	-	-	0.00 – 0.10	0.10 - 0.40	0.40 - 2.20	2.20 – 2.50	-
TP304	-	-	0.00 – 0.15	0.15 – 0.40	0.40 – 1.50	1.50 - 2.40 <b>^</b>	-
TP306	-	-	0.00 – 0.18	-	0.18 – 0.36	-	0.36 - 0.90
TP307	-	-	0.00 – 0.20	-	0.20 - 2.00	2.00 - 2.30^	-
TP308	-	-	0.00 – 0.15	0.15 – 0.40	0.40 – 1.10	1.10 – 1.60	1.60 – 1.70 <b>^</b>
TP309	-	-	0.00 – 0.15	-	0.15 – 1.60	1.60 – 2.00	2.00 - 2.20 <b>^</b>
TP310	-	-	0.00 - 0.14	0.14 - 0.40	-	-	0.40 - 0.85*
TP312	-	-	0.00 – 0.17	-	0.17 – 1.70	-	1.70 – 1.80*
Notes:	* = Practical refus	sal or refusal of exco	avator met on High	ly Weathered Rock			
	$\wedge$ = Slow to very s	low progress, close	to practical excav	ator refusal.			

No groundwater levels or water inflows were encountered in the test pits during the limited time that they remained open on the day of the field investigations.

It should be noted that groundwater conditions can vary due to rainfall and other influences including regional groundwater flow, temperature, permeability, recharge areas, surface condition, and subsoil drainage.

29 April 2020 8 NEW15P-0070B-AK

## 5.0 Laboratory Testing

Samples collected during the current field investigations were returned to our NATA accredited Warabrook Laboratory for testing which comprised of:

• (14 no.) Shrink / Swell tests.

Results of the laboratory testing are presented in Appendix B, with a summary of the Shrink/Swell test results presented in Table 3.

The tables also include a summary of laboratory testing information (where applicable) from the previous Geotechnical Assessment works carried out by Qualtest.

TABLE 3 - SUMMARY OF SHRINK / SWELL TESTING RESULTS

Location	Depth (m)	Material Description	Iss (%)
		Current Investigation	
TP1501	0.50 – 0.60	FILL: (CI) Gravelly Sandy CLAY	0.7
TP1502	0.95 – 1.10	FILL: (CL) Gravelly Sandy CLAY	0.2
TP1503	0.35 – 0.60	FILL: (CL) Gravelly Sandy CLAY	0.5
TP1505	0.50 – 0.65	FILL: (CL) Gravelly Sandy CLAY	0.7
TP1506	0.90 – 1.05	(CH) Sandy CLAY	2.4
TP1507	0.20 - 0.35	FILL: (CL) Gravelly Sandy CLAY	1.1
TP1508	0.20 - 0.35	FILL: (CL) Gravelly Sandy CLAY	0.5
TP1509	0.30 - 0.50	(CH) Sandy CLAY	2.3
TP1510	0.30 – 0.55	FILL: (CI) Gravelly Sandy CLAY	3.1
TP1510	0.60 - 0.80	(CH) Sandy CLAY	3.0
TP1512	0.60 - 0.80	FILL: (CL) Gravelly Sandy CLAY	0.6
TP1513	0.50 – 0.70	(CH) Sandy CLAY	1.6
TP1514	0.50 – 0.95	FILL: (CI) Gravelly Sandy CLAY / Sandy CLAY	1.3
TP1515	0.40 – 0.55	FILL: (CL) Gravelly Sandy CLAY	0.4
Pr	evious Investiga	tion (NEW15P-0070B-AB.Rev1, dated 26 June 20	17)
TP302	0.40 – 0.70	(CI) Sandy CLAY	2.7
TP303	0.60 - 0.80	(CH) Sandy CLAY	2.4
TP309	0.50 - 0.80	(CH) Sandy CLAY	1.7

TABLE 4 - SUMMARY OF ATTERBERG LIMITS TESTING RESULTS

Location	Sample Depth (m)	Material Description	Liquid Limit (%)	Plastic limit (%)	Plasticity Index (%)	Linear Shrinkage (%)
TP306	0.20 - 0.30	(CH) Sandy CLAY	46	19	27	10.0
TP307	0.20 - 0.40	(CH) Sandy CLAY	67	24	43	12.0
TP308	0.50 – 0.70	(CH) Sandy CLAY	52	18	34	9.0

#### 6.0 Site Classification to AS2870-2011

Based on the results of the field work and laboratory testing, and Level 1 site supervision and testing carried out, residential lots located within Stage 15 of the Billy's Lookout subdivision at Fishermans Drive, Teralba, as shown on Figure AK1, are classified in their current condition in accordance with AS2870-2011 'Residential Slabs and Footings', as shown in Table 5.

TABLE 5 - SITE CLASSIFICATION TO AS2870-2011

Lot Numbers	Site Classification
1501 to 1530	Н1

A characteristic free surface movement of 40mm to 60mm is estimated for the lots classified as **Class 'H1'** in their existing condition.

The effects of changes to the soil profile by additional cutting and filling and the effects of past and future trees should be considered in selection of the design value for differential movement. If site re-grading works involving cutting or filling are performed after the date of this assessment the classification may change and further advice should be sought.

Final site classification will be dependent on a number of factors, including depth of topsoil, depth of cut / fill, reactivity of the natural soil and any fill material placed, depth to rock, and the level of supervision carried out. Re-classification of lots should be confirmed by the geotechnical authority at the time of construction following any site re-grade works.

Footings for the proposed development should be designed and constructed in accordance with the requirements of AS2870-2011.

The classification presented above assumes that:

- All footings are founded in controlled fill (if applicable) or in the residual clayey soils or rock below all non-controlled fill, topsoil material and root zones, and fill under slab panels meets the requirements of AS2870-2011, in particular, the root zone must be removed prior to the placement of fill materials beneath slabs;
- The performance expectations set out in Appendix B of AS2870-2011 are acceptable, and that site foundation maintenance is undertaken to avoid extremes of wetting and drying;
- Footings are to be founded outside of or below all zones of influence resulting from existing or future service trenches;
- The constructional and architectural requirements for reactive clay sites set out in AS2870-2011 are followed;

- Adherence to the detailing requirement outlined in Section 5 of AS2870-2011 'Residential Slabs and Footings' is essential, in particular Section 5.6, 'Additional requirements for Classes M, H1, H2 and E sites' including architectural restrictions, plumbing and drainage requirements; and,
- Site maintenance complies with the provisions of CSIRO Sheet BTF 18, "Foundation Maintenance and Footing Performance: A Homeowner's Guide", a copy of which is attached in Appendix C.

All structural elements on all lots should be supported on footings founded beneath all uncontrolled fill, layers of inadequate bearing capacity, soft/loose, wet or other potentially deleterious material.

If any localised areas of uncontrolled fill of depths greater than 0.4m are encountered during construction, footings should be designed in accordance with engineering principles for Class 'P' sites.

#### 7.0 Limitations

The findings presented in the report and used as the basis for recommendations presented herein were obtained using normal, industry accepted geotechnical design practices and standards. To our knowledge, they represent a reasonable interpretation of the general conditions of the site.

The extent of testing associated with this assessment is limited to discrete test pit locations. It should be noted that subsurface conditions between and away from the test pit locations may be different to those observed during the field work and used as the basis of the recommendations contained in this report.

If subsurface conditions encountered during construction differ from those given in this report, further advice should be sought without delay.

Data and opinions contained within the report may not be used in other contexts or for any other purposes without prior review and agreement by Qualtest. If this report is reproduced, it must be in full.

If you have any further questions regarding this report, please do not hesitate to contact Ben Bunting, Shannon Kelly, or the undersigned.


For and on behalf of Qualtest Laboratory (NSW) Pty Ltd.

Jason Lee

Principal Geotechnical Engineer

# FIGURE AK1:

Site Plan and Approximate Test Locations





Client:	MCCLOY DEVELOPMENT MANAGEMENT PTY LTD	Drawing No:	FIGURE AK1
Project:	BILLY'S LOOKOUT - STAGE 15	Project No:	NEW15P-0070B
Location:	FISHERMANS DRIVE, TERALBA	Scale:	N.T.S.
Title:	SITE PLAN AND APPROXIMATE TEST LOCATIONS	Date:	29/4/2020

# **APPENDIX A:**

**Results of Field Investigations** 



: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD **PAGE**:

**PROJECT**: BILLYS LOOKOUT - STAGE 15 **JOB NO**: NEW15P-0070B

LOCATION: FISHERMANS DRIVE, TERALBA

**DATE**: 7/4/20

TEST PIT NO:

LOGGED BY:

**TP1501** 

1 OF 1

ВВ

		T LENGT		2.0 m		IDTH:		JM:					
	Drill	ing and San	npling				Material description and profile information				Field	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticit characteristics,colour,minor componen		MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
				-		CL	FILL-TOPSOIL: Sandy CLAY - low plasticit grey-brown, fine to medium grained sand, v mulch.		M > W				FILL - TOPSOIL
		0.50m		0.5_			FILL: Gravelly Sandy CLAY - medium plast orange-brown, fine to coarse grained (mos medium grained) sand, fine to coarse grain angular to sub-angular gravel, trace cobble	tly fine to ed			HP	420	FILL - CONTROLLED
		U50 (0.60m		-					M ~ W <sub>P</sub>		HP	450	
В	Not Encountered			1.0			Brown to pale brown.				HP	>600 >600	
	Not			-		CI				VSt - H	HP	>600	
				1. <u>5</u>					M < W <sub>P</sub>		HP	>600	
				-			Grey-brown.				HP	>600 >600	
				2.0			2.00m Hole Terminated at 2.00 m						
				-									
LEG	GEND:			Notes, Sa				Consiste				CS (kPa	-
	Wat (Dat Wat	er Level te and time sl er Inflow er Outflow	hown)	U <sub>50</sub> CBR E	Bulk s Enviro (Glass Acid S	ample t nmenta i jar, se Sulfate S	ter tube sample or CBR testing al sample aled and chilled on site) Soil Sample air expelled, chilled)	S S F F St S VSt V	ery Soft oft irm stiff ery Stiff lard		25 50 10 20	25 5 - 50 0 - 100 00 - 200 00 - 400	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit W <sub>L</sub> Liquid Limit
Stra	ta Cha G tra De	anges radational or ansitional stra efinitive or dis rata change	ata	B Field Tesi PID DCP(x-y) HP	Bulk S ts Photoi Dynan	ample ionisationic pen	on detector reading (ppm) etrometer test (test depth interval shown) ometer test (UCS kPa)	1	riable V L ME D VD	Lo D D	ery Lo	oose n Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%



IT: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

**LOCATION**: FISHERMANS DRIVE, TERALBA **LOGGED BY**: BB

**DATE**: 7/4/20

TEST PIT NO:

**TP1502** 

1 OF 1

		T LENGTI		2.0 m		IDTH:		JM:					
	Drill	ing and San	npling				Material description and profile information				Fiel	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity characteristics, colour, minor component		MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
				-		CL	FILL-TOPSOIL: Sandy CLAY - low plasticity grey-brown, fine to coarse grained (mostly i medium grained) sand, with some mulch.  0.25m  FILL: Sandy CLAY - medium plasticity, pale red-brown to orange-brown, fine to coarse	fine to	M > W <sub>P</sub>	St			FILL - CONTROLLED
Ш	Not Encountered	0.95m U50 1.10m		- 0.5		CL	sand.  FILL: Gravelly Sandy CLAY - low to mediur plasticity, pale orange-brown, fine to coarse (mostly fine to medium grained) sand, fine t grained angular to sub-angular gravel, trace	e grained to coarse	M ~ W <sub>P</sub>	VSt - H	HP HP HP HP	500 >600 580 470 530 >600	
				2.0		CH	Grey-brown.  1.80m  Sandy CLAY - medium to high plasticity, gn some pale brown, fine to medium grained s  2.00m  Hole Terminated at 2.00 m			VSt	HP	>600	RESIDUAL SOIL — — —
Wat	Wat (Dai - Wat I Wat ata Cha G tra	er Level te and time sl ter Inflow ter Outflow anges radational or ansitional stra efinitive or dis rata change	hown) ata	Notes, Sa U <sub>50</sub> CBR E ASS B Field Test PID DCP(x-y)	50mm Bulk s Enviro (Glass Acid S (Plasti Bulk S Photoi Dynan	Diame ample to nomenta s jar, se Sulfate S c bag, se c bag, se conisationic pen	ter tube sample or CBR testing Il sample aled and chilled on site) soil Sample air expelled, chilled) on detector reading (ppm) etrometer test (test depth interval shown) meter test (UCS kPa)	S So F Fi St St VSt Vo H H	ery Soft oft irm tiff ery Stiff ard riable  V  L  ME  D  VD	V Lo D	25 50 10 20 20 20 ery Lo	n Dense	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit W <sub>L</sub> Liquid Limit  Density Index <15% Density Index 15 - 35%



MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

PROJECT: BILLYS LOOKOUT - STAGE 15 JOB NO: NEW15P-0070B

LOCATION: FISHERMANS DRIVE, TERALBA

LOGGED BY: DATE: 7/4/20

TEST PIT NO:

**TP1503** 

1 OF 1

ВВ

EQUIPMENT TYPE: TEST PIT LENGTH:				2.7 TONNE EXCAVATOR 2.0 m WIDTH: 0.5 m				SURF DATU	ACE RL:					
		ing and Sam						ion and profile information				Field	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCI	RIPTION: Soil type, plasticity tics,colour,minor component	//particle	MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additiona observations
				-		sc	coarse grained, of low plasticity,	: Clayey SAND / Sandy CLA , grey-brown to pale grey-bro , with some fine to medium g angular gravel, with some m	own, fines grained	M - W				FILL - TOPSOIL
		0.35m U50		0.5			FILL: Gravelly S plasticity, pale of (mostly fine to r	Sandy CLAY - low to medium orange-brown, fine to coarse medium grained) sand, fine to r to sub-angular gravel.	grained			HP	>600	FILL - CONTROLLED
		0.60m		-		CL						HP	>600	
Е	Not Encountered			-								HP	>600	
	No	1.10m		1. <u>0</u>				medium to high plasticity, grevn, fine to medium grained s		M < W	VSt - H	HP	>600	RESIDUAL SOIL
		U50 1.25m		-			Pale orange-bro	own.				HP		
				1. <u>5</u>		CH						HP		
				_			Pale grey and p	oale red-brown.				пР	>000	
				2.0			Hole Terminate Slow progress	d at 1.80 m						
				-										
				-										
Wate	Wat (Dat Wat	er Level e and time she er Inflow er Outflow	own)	Notes, Sal U <sub>50</sub> CBR E	50mm Bulk s Enviro (Glass Acid S (Plasti	Diame ample in nmenta jar, se sulfate s c bag,	ts eter tube sample for CBR testing al sample saled and chilled on site) Soil Sample air expelled, chilled)		S S F F St S VSt V H F	ery Soft Soft Firm Stiff ery Stiff		25 50 10 20	CS (kPa 25 5 - 50 0 - 100 00 - 200 00 - 400 400	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit
Stra	tra De	anges radational or ansitional strat efinitive or dist rata change		B Field Test PID DCP(x-y) HP	<u>s</u> Photoi Dynan	nic pen	on detector reading (ppm etrometer test (test depth ometer test (UCS kPa)		Fb F <u>Density</u>	Friable V L ME D VD	Lo D D	ery Lo oose ediun ense ery Do	n Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%



CLIENT: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

PROJECT: BILLYS LOOKOUT - STAGE 15 JOB NO: NEW15P-0070B

**TP1504** 

1 OF 1

BB

**TEST PIT NO:** 

LOGGED BY:

VD

Very Dense

Density Index 85 - 100%

LOCATION: FISHERMANS DRIVE, TERALBA

DATE: 7/4/20 **EQUIPMENT TYPE:** 2.7 TONNE EXCAVATOR SURFACE RL: **TEST PIT LENGTH:** 2.0 m WIDTH: DATUM: Drilling and Sampling Field Test Material description and profile information CLASSIFICATION SYMBOL CONSISTENCY DENSITY GRAPHIC LOG Test Type Structure and additional METHOD WATER Result DEPTH MATERIAL DESCRIPTION: Soil type, plasticity/particle observations SAMPLES (m) (m) characteristics, colour, minor components FILL - TOPSOIL FILL-TOPSOIL: Clayey SAND / Sandy CLAY - fine to coarse grained, grey-brown, fines of low plasticity, SC with some sticks and mulch. FILL - CONTROLLED FILL: Gravelly Clayey SAND / Gravelly Sandy CLAY - fine to coarse grained (mostly fine to medium grained), low plasticity, pale orange-brown, fine to coarse grained angular to sub-angular gravel, trace cobbles. 0.5 SC D - VD Μ 0.80m D 0.90m Encountered ш TEST PIT NEW15P-0070B-AK DRAFT LOGS.GPJ <<DrawingFile>> 28/04/2020 19:56 10.0.000 Datgel Lab and In Situ Tool Мod 1.20m FILL: Gravelly Sandy CLAY - low to medium plasticity, pale orange-brown, fine to coarse grained (mostly fine to medium grained) sand, fine to coarse grained angular to sub-angular gravel, trace cobbles. U50 ΗP >600 1.35m VSt CL 1.5 ΗP >600 RESIDUAL SOIL Sandy CLAY - medium to high plasticity, grey with some pale brown, fine to medium grained sand. HP 350 Grey-brown. CH VSt HP 350 EXTREMELY WEATHERED ROCK Extremely Weathered Sandstone with soil properties; breaks down into Sandy CLAY - medium plasticity, CI Н orange-brown and pale grey, fine to medium grained Hole Terminated at 2.15 m LEGEND: Notes, Samples and Tests Consistency UCS (kPa) **Moisture Condition** 50mm Diameter tube sample Very Soft V.S <25 D Dry Water CBR Bulk sample for CBR testing 25 - 50 Moist S Soft М Water Level Ε Environmental sample F Firm 50 - 100 W Wet (Date and time shown) (Glass jar, sealed and chilled on site) St Stiff 100 - 200 W. Plastic Limit Water Inflow ASS Acid Sulfate Soil Sample VSt Very Stiff 200 - 400  $W_L$ Liquid Limit ■ Water Outflow (Plastic bag, air expelled, chilled) Н Hard >400 В Bulk Sample Fb Friable Strata Changes Field Tests **Density** Very Loose Density Index <15% Gradational or PID Photoionisation detector reading (ppm) Loose Density Index 15 - 35% transitional strata DCP(x-y) Dynamic penetrometer test (test depth interval shown) MD Medium Dense Density Index 35 - 65% Definitive or distict HP Hand Penetrometer test (UCS kPa) Density Index 65 - 85% strata change



IENT: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

**TP1505** 

1 OF 1

TEST PIT NO:

LOCATION: FISHERMANS DRIVE, TERALBALOGGED BY:BBDATE:7/4/20

		IENT TYPI T LENGTH		2.7 TC 2.0 m		EXCA I <b>DTH</b> :		RFACE RL: 'UM:					
		ing and Sam					Material description and profile information	information				d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plastic characteristics,colour,minor compone	ity/particle nts	MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
				_		SC	FILL-TOPSOIL: Clayey SAND / Sandy Cl coarse grained, grey-brown, fines of low with some fine to medium grained angula	olasticity, r to	× × ×				FILL - TOPSOIL
		0.50m U50 0.65m		- 0. <u>5</u>			o.15m sub-angular gravel, with some sticks and FILL: Gravelly Sandy CLAY - low plasticit orange-brown, fine to coarse grained (momedium grained) sand, fine to coarse gra angular to sub-angular gravel.	y, pale stly fine to			HP		FILL - CONTROLLED
ш	Not Encountered			1. <u>0</u>		CL			M < wp	VSt - H	HP	490 >600	
				- 1. <u>5</u> - -		CH	Sandy CLAY - medium to high plasticity, some pale brown, fine to medium grained some roots.  Orange-brown with some grey-brown.		M ~ Wp	VSt		300	RESIDUAL SOIL
				2.0			2.00m		M × W	Н			
				-			Hole Terminated at 2.00 m						
<u>Wat</u>	Wat (Dat Wat	er Level se and time sh er Inflow er Outflow	nown)	Notes, Sa U <sub>50</sub> CBR E	50mm Bulk s Enviro (Glass Acid S	Diame ample to nmenta jar, se sulfate s	L ts ster tube sample for CBR testing al sample saled and chilled on site) Soil Sample air expelled, chilled)	S S F F St S VSt V	ncy /ery Soft Soft Firm Stiff /ery Stiff		25 50 10 20	CS (kPa 25 5 - 50 0 - 100 00 - 200 00 - 400 400	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit
	ta Cha G tra De			B Field Test PID DCP(x-y) HP	Bulk S ss Photoi Dynan	ample onisationic pen		1	riable V L ME D VD	Lo D D	ery Lo	oose n Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%



NT: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT**: BILLYS LOOKOUT - STAGE 15 **JOB NO**: NEW15P-0070B

LOCATION: FISHERMANS DRIVE, TERALBA

**DATE**: 7/4/20

TEST PIT NO:

LOGGED BY:

**TP1506** 

1 OF 1

ВВ

		IENT TYPI IT LENGTI		2.7 TC 2.0 m		EXCA ' <b>IDTH</b> :		FACE RL: JM:					
	Drill	ing and San	npling				Material description and profile information				Fiel	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticit characteristics,colour,minor componen		MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
				_		CL	FILL-TOPSOIL: Sandy CLAY - low to medi plasticity, grey-brown, fine to coarse graine with some sticks and mulch.	um d sand,	M ∨ M				FILL - TOPSOIL
		0.35m U50		-		CL	FILL: Gravelly Sandy CLAY - low to mediui plasticity, pale orange-brown, fine to coarse (mostly fine to medium grained) sand, fine grained angular to sub-angular gravel, trace	e grained to coarse	1 ~ W <sub>P</sub>		HP	180	FILL - CONTROLLED
		0.50m		0. <u>5</u>			0.60m		Σ	St	HP	200	
				_		CL ——-	Sandy CLAY - low to medium plasticity, da grey-brown, fine to medium grained sand.  Sandy CLAY - medium to high plasticity, orange-brown with some red-brown, fine to		× × ×		HP	150	RESIDUAL SOIL
	Encountered	0.90m		-			grained sand.				HP	500	
Ш Iool про	Not Enc	U50 1.05m		1.0_							HP	>600	
cozo 19:56 10.0.000 Datgel Lab and In				- 1. <u>5</u>		CH	Red-brown and pale grey.		M < W	н	HP		
15.5.GPJ < <drawingfile>&gt; 28/04/2</drawingfile>				- - 2.0			2.00m				HP	>600	
SI PII NEWISP-UV. UB-AN DRAFT L				-			Hole Terminated at 2.00 m						
May	Wat (Dai - Wat Wat - G G	er Level te and time sl ter Inflow ter Outflow anges radational or ansitional stra efinitive or dis rata change	nta	Notes, Sa U <sub>50</sub> CBR E ASS B Field Test PID DCP(x-y) HP	50mm Bulk s Enviro (Glass Acid s (Plast Bulk s s Photo Dynar	n Diame sample f ponmenta s jar, se Sulfate S ic bag, a Sample ionisationic pene	ter tube sample or CBR testing all sample alled and chilled on site) Soil Sample air expelled, chilled) on detector reading (ppm) etrometer test (test depth interval shown) ometer test (UCS kPa)	S S F F St S VSt V H F	ncy /ery Soft /ort /ery Stiff /ery Stiff /ery Stiff /ard /riable  V L ME D VD	V L	25 50 10 20 20 20 ery Lo	n Dense	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit Liquid Limit  Density Index <15% Density Index 15 - 35%



IT: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

**LOCATION:** FISHERMANS DRIVE, TERALBA **LOGGED BY:** 

**DATE**: 7/4/20

TEST PIT NO:

**TP1507** 

1 OF 1

ВВ

		MENT TYP						ACE RL:					
		T LENGT		2.0 m	VVI	DTH:		JIVI:			F		
	Dril	ing and Sar	npling		()	NOI	Material description and profile information		<i>7</i>			d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticit characteristics,colour,minor componen	y/particle ts	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
						CL	FILL-TOPSOIL: Sandy CLAY - low to medii plasticity, grey-brown, fine to coarse graine						FILL - TOPSOIL
		0.20m U50 0.35m		- - 0. <u>5</u>		CL	with some sticks and mulch.  FILL: Gravelly Sandy CLAY - low to mediur plasticity, pale orange-brown, fine to coarse (mostly fine to medium grained) sand, fine grained angular to sub-angular gravel, trace	grained to coarse	M > W <sub>P</sub>	VSt	HP	300	FILL - CONTROLLED
	ered			-		CL	FILL: Gravelly Sandy CLAY / Gravelly Clay - low plasticity, pale orange-brown, fine to o grained (mostly fine to medium grained) sa coarse grained angular to sub-angular grav cobbles.	oarse nd, fine to	M ~ W <sub>P</sub>				
ш	Not Encountered			1. <u>0</u>	*** /// ///	SC	Clayey SAND - fine to medium grained, dai to dark grey-brown, fines of low plasticity.	k brown	D - M	D			COLLUVIUM
טט באייט ווו סוויס ווי סוויס ווי				-			Sandy CLAY - medium to high plasticity, gr some pale brown, fine to medium grained s				HP	380	RESIDUAL SOIL
255 ZOJUNIZUZU 18:00 19:00				1. <u>5</u>		СН	Red-brown and pale grey to white.		M > w <sub>P</sub>	VSt	HP	350	
Go.GPJ vvDlawiignis				2.0			2.00m				HP	300	
1 FILINEW 101-100 100-101 INEW 101-101 101-101 INEW 101-101-101-101-101-101-101-101-101-101				-			Hole Terminated at 2.00 m						
Wat	. War (Da - War ¶ War ata Ch G	radational or ansitional stra	hown)	Notes, Sa U <sub>50</sub> CBR E ASS B Field Test PID DCP(x-y)	50mm Bulk si Enviro (Glass Acid S (Plasti Bulk S	Diame ample nmenta jar, se ulfate c bag, ample onisati	ts ter tube sample for CBR testing all sample aled and chilled on site) Soil Sample air expelled, chilled) on detector reading (ppm) etrometer test (test depth interval shown)	S So F Fin St St VSt Ve H Ha	ery Soft oft m	V	25 50 10 20 20 20 ery Lo	CS (kPa) 25 5 - 50 0 - 100 00 - 200 00 - 400 400 pose	Moisture Condition D Dry M Moist W Wet Wp Plastic Limit WL Liquid Limit  Density Index <15% Density Index 15 - 35% Density Index 35 - 65%
		efinitive or dis rata change	stict	HP			ometer test (UCS kPa)		D VD	D	ense ery D		Density Index 65 - 85% Density Index 85 - 100%



MCCLOY DEVELOPMENT MANAGEMENT PTY LTD **PAGE**:

NEW15P-0070B JOB NO:

**TP1508** 

1 OF 1

LOCATION: FISHERMANS DRIVE, TERALBA

LOGGED BY: ВВ

TEST PIT NO:

DATE: 7/4/20

		MENT TYPI IT LENGTI		2.7 TC 2.0 m		EXCA I <b>DTH</b> :		FACE RL: JM:					
	Drill	ing and San	npling				Material description and profile information				Field	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plastici characteristics,colour,minor componer	ty/particle its	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
				-			MULCH		M				MULCH
		0.20m U50 0.35m		- 0.5		CL	FILL: Gravelly Sandy CLAY - low to mediu plasticity, pale orange-brown, fine to coars (mostly fine to medium grained) sand, fine grained angular to sub-angular gravel, trace	e grained to coarse	M ~ M	VSt	HP HP	350 400	FILL - CONTROLLED
	pe			0.5_		SC	Clayey SAND - fine to medium grained, da 0.60m grey-brown, fines of low plasticity.  Sandy CLAY - medium to high plasticity, p		D - M	MD	HP	400	COLLUVIUM  RESIDUAL SOIL
Е	Not Encountered			-			orange-brown and pale grey, fine to mediu sand, with some roots.	m grained		VSt -	HP	380	
				1. <u>0</u>		СН			M ~ W <sub>P</sub>	H	HP	500	
				-			Sandy CLAY - medium to high plasticity, p orange-brown and pale grey, fine to mediu sand, with relict rock structure.		_	Н	HP	>600	RESIDUAL SOIL / EXTREMELY WEATHERED ROCK
				1. <u>5</u>			1.55m 1.60m Silty SANDSTONE - fine grained, orange-l		D - M	""	HP	>600	EXTREMELY TO HIGHLY
				-			pale grey, estimated very low to low streng Hole Terminated at 1.60 m Very slow progress	th.					WEATHERED ROCK
				2.0_									
				-									
Wat	Wat (Dat Wat Wat	er Level te and time sl er Inflow er Outflow	nown)	Notes, Sa U <sub>50</sub> CBR E ASS	50mm Bulk s Enviro (Glass Acid S	Diame ample i nmenta jar, se ulfate s c bag,	ts ter tube sample for CBR testing al sample aled and chilled on site) Soil Sample air expelled, chilled)	S So F Fir St Sti VSt Ve H Ha	ery Soft oft m		25 50 10 20	CS (kPa 25 5 - 50 0 - 100 00 - 200 00 - 400	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit
<u>ətra</u>	G tra D	anges radational or ansitional stra efinitive or dis rata change		Field Test PID DCP(x-y) HP	<u>:s</u> Photoi Dynan	onisationic pen	on detector reading (ppm) etrometer test (test depth interval shown) ometer test (UCS kPa)	<u>Density</u>	V L ME D VD	L( ) N D	ery Lo oose ledium ense ery De	n Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%



ENT: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

LOCATION: FISHERMANS DRIVE, TERALBA

**DATE**: 7/4/20

TEST PIT NO:

LOGGED BY:

**TP1509** 

1 OF 1

ВВ

		T LENGTH ing and Sam		2.0 m		IDTH:	0.5 m DATU  Material description and profile information				Field	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticit characteristics, colour, minor componen		MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additiona observations
	Encountered	0.30m		-		sc	FILL-TOPSOIL: Clayey SAND - fine to coal grained, dark grey, fines of low plasticity, w mulch.	ith some	M - W				FILL - TOPSOIL
Е	Not En	U50 0.50m		0.5_		CH — — - CH	Sandy CLAY - medium to high plasticity, pa orange-brown with some pale grey, fine to grained sand.    Extremely Weathered Silty Sandstone with properties; breaks down into Sandy CLAY to high plasticity, pale orange-brown with so	medium soil - medium	M < W → M - M	VSt - H	HP HP	430 >600	EXTREMELY WEATHERE ROCK  EXTREMELY TO HIGHLY
				1.0			grey, fine to medium grained sand.  Sitty SANDSTONE - fine grained, pale grey orange-brown, estimated very low to low st Hole Terminated at 0.65 m Practical Refusal						WEATHERED ROCK
Wat	Wat (Dat Wat Wat I Wat	er Level te and time sho er Inflow er Outflow anges radational or	own)	Notes, Sal U <sub>50</sub> CBR E ASS B Field Test	50mm Bulk s Enviro (Glass Acid S (Plasti Bulk S	Diame ample to nmenta i jar, se sulfate s c bag, a tample	ter tube sample for CBR testing al sample aled and chilled on site) Soil Sample air expelled, chilled)	S S F F St S VSt V	/ery Soft Soft Firm Stiff /ery Stiff lard Friable V	·	25 50 10 20 >4 ery Lo	5 - 50 0 - 100 00 - 200 00 - 400	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit W <sub>L</sub> Liquid Limit  Density Index <15%
	_ D	ansitional strat efinitive or dist rata change		PID DCP(x-y) HP	Dynan	nic pen	on detector reading (ppm) etrometer test (test depth interval shown) ometer test (UCS kPa)		L ME D VC	) N D	oose lediun ense ery De	n Dense ense	Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%



LIENT: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

**LOCATION:** FISHERMANS DRIVE, TERALBA **LOGGED BY:** 

**DATE**: 7/4/20

TEST PIT NO:

**TP1510** 

1 OF 1

ВВ

		IT LENGTI		2.0 m		DTH:		JM:					
	Dril	ling and San	npling				Material description and profile information				Field	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticit characteristics,colour,minor componen		MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
		0.30m		-		SC	FILL-TOPSOIL: Clayey SAND - fine to coa grained, grey-brown, fines of low plasticity, sticks and mulch.		M - W			100	FILL - TOPSOIL
		U50 0.55m		0.5_		CI	FILL: Gravelly Sandy CLAY - medium plast orange-brown, fine to coarse grained (mos medium grained) sand, fine to coarse grain angular to sub-angular gravel, trace cobble	tly fine to led ss.		St - VSt	HP	300	FILL - CONTROLLED
Ш	Not Encountered	0.60m U50 0.80m		-		СН	Sandy CLAY - medium to high plasticity, parorange-brown to pale brown, fine to mediun sand.		M > W <sub>P</sub>	VSt	HP	350	RESIDUAL SOIL
001	NON			1. <u>0</u>			1.10m				HP	320	EXTREMELY WEATHERED
awiigriezz zolułizzzo 19:30 Tutuou Dalgertadaliu ii silu Tod				- - 1.5		CL	Extremely Weathered Sandstone with soil breaks down into Gravelly Sandy CLAY - Ic medium plasticity, pale orange-brown and fine to coarse grained (mostly fine to mediugrained) sand, fine to medium grained ang gravel.	ow to cale grey, im	M < W <sub>P</sub>	Н	HP HP	>600 >600	ROCK
06.96				1.5_	<i>(//////</i>		Silty SANDSTONE - fine grained, grey to p estimated very low to low strength.	ale grey,	D - M				EXTREMELY TO HIGHLY WEATHERED ROCK
THE INTEREST OF THE PROPERTY O				- 2. <u>0</u> - -			Hole Terminated at 1.60 m Practical Refusal						
Wat  Stra	Wat (Da	ter Level te and time sl ter Inflow ter Outflow anges	hown)	Notes, Sa  U <sub>50</sub> CBR E  ASS	50mm Bulk sa Enviro (Glass Acid S	Diame ample inmenta jar, se ulfate s bag,	Ester tube sample or CBR testing Il sample Soil Sample Soil Sample alse sample	S S F F St S VSt V H H	ncy ery Soft oft irm tiff ery Stiff lard riable		25 50 10 20	CS (kPa 25 5 - 50 0 - 100 00 - 200 00 - 400	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit
	G tra D	radational or ansitional stra efinitive or dis rata change		Field Test PID DCP(x-y) HP	<u>ts</u> Photoi Dynan	onisationic pen	on detector reading (ppm) etrometer test (test depth interval shown) meter test (UCS kPa)	<u>Density</u>	V L MD D VD	Lo M D	ery Lo oose edium ense ery De	n Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%



: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

TP1511

1 OF 1

TEST PIT NO:

LOCATION: FISHERMANS DRIVE, TERALBALOGGED BY:BBDATE:7/4/20

		T LENGTH:		2.0 m	VV	IDTH:	0.5 m DATU  Material description and profile information	INI:			Fiel	d Test	
	ااا ا		19			z				Γ.	1. 101		
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity characteristics,colour,minor component	//particle s	MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additiona observations
		0.05m U50		-		CL	FILL: Gravelly Sandy CLAY - low to mediun plasticity, pale orange-brown, fine to coarse (mostly fine to medium grained) sand, fine to	grained o coarse	× × ×	VSt			FILL - CONTROLLED
ш	Not Encountered	<u>0.15m</u>		- - 0.5		CI	0.15m grained angular to sub-angular gravel, trace 0.20m Sandy CLAY - medium plasticity, orange-br to coarse grained sand.  Extremely Weathered Sandstone with soil p breaks down into Sandy CLAY - medium pl orange-brown, fine to coarse grained sand.	rown, fine   properties; asticity,	M < W <sub>p</sub>	Н	HP	>600	RESIDUAL SOIL EXTREMELY WEATHER! ROCK
							SANDSTONE - fine to medium grained, orange-brown to red-brown with some pale white, estimated very low to low strength.	grey to	D				EXTREMELY TO HIGHLY WEATHERED ROCK
				-			Hole Terminated at 0.60 m Practical Refusal	/					
				-									
				-									
				1.0_									
				-									
				_									
				_									
				1.5_									
				_									
				_									
				-									
				2.0_									
				-									
				-									
	END:	'	1	Notes, Sai			ts ter tube sample	Consister VS V	ncy ery Soft		_	<b>CS (kPa</b> 25	Moisture Condition D Dry
Wate	_	er Level		CBR	Bulk s	ample f	or CBR testing	s s	oft		2	5 - 50	M Moist
_ 	(Dat	e and time sho er Inflow	1	E ASS	(Glass Acid S	s jar, se Sulfate S	al sample aled and chilled on site) Soil Sample	St S VSt V	irm stiff ery Stiff		10 20	0 - 100 00 - 200 00 - 400	P
<b>√</b> Stra		er Outflow anges		В		ic bag, a Sample	air expelled, chilled)	1	lard riable		>4	400	
	G tra	radational or ansitional strata efinitive or disti	,	Field Test PID DCP(x-y)	<u>s</u> Photoi	ionisatio	on detector reading (ppm) etrometer test (test depth interval shown)	Density	V L ME	L	ery Lo oose lediur	oose n Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65%
		rata change	οι 	HP			ometer test (UCS kPa)		D VD		ense ery D	ense	Density Index 65 - 85% Density Index 85 - 100%



**CLIENT:** MCCLOY DEVELOPMENT MANAGEMENT PTY LTD **PAGE**:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

LOCATION: FISHERMANS DRIVE, TERALBA

**DATE**: 7/4/20

TEST PIT NO:

LOGGED BY:

TP1512

1 OF 1

ВВ

TE	ST P	T LENGTH	l:	2.0 m	W	IDTH:	0.5 m <b>DATU</b>	JM:					
	Drill	ing and Sam	pling				Material description and profile information				Field	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticit characteristics,colour,minor componen	y/particle ts	MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
				-			FILL: Gravelly Sandy CLAY - low plasticity, orange-brown, fine to coarse grained (mos medium grained) sand, fine to coarse grain angular to sub-angular gravel, trace cobble	tly fine to led	M > W <sub>P</sub>	St - VSt	HP	150	FILL - CONTROLLED
		0.60m U50 0.80m		0. <u>5</u> -							HP		
nd in Situ Tool	Not Encountered	<u>U.OUIII</u>		1.0_ -		CL	Pale brown.		. W √	VSt -	HP	>600 >600	
OT LIB 11.1GEB. Log NON-CORED BORRHOLE - TEST PIT NEW15P-0070B-AK DRAFT LCGS.GFJ <<0 mm/s/rie> 28/04/2020 19:56 10:0:000 Datgel. Lab and in Sifu Tool in Sign 10:01   In Sign				1. <u>5</u>			2.00m		W	Н	HP		
ESI PII NEWISP-UV/UB-AN URAFI LOGO				-	XXX		Hole Terminated at 2.00 m						
Mary Stra	Wat (Dai - Wat Wat - G G tra	er Level te and time sh er Inflow er Outflow anges radational or ansitional strat efinitive or dis rata change	own)	Notes, Sal U <sub>50</sub> CBR E ASS B Field Test PID DCP(x-y) HP	50mm Bulk s Enviro (Glass Acid S (Plasti Bulk S S Photo Dynar	Diamet ample for nmenta a jar, sea sulfate S c bag, a ample onisation	E er tube sample or CBR testing I sample I sampl	S S F F St S VSt V H F	ncy Very Soft oft oft irm diff very Stiff lard riable V L MC	V L	<2 25 50 10 20 >2 ery Lo	5 - 50 0 - 100 00 - 200 00 - 400 400	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit U Liquid Limit Density Index <15% Density Index 15 - 35%



MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

LOCATION: FISHERMANS DRIVE, TERALBA

**DATE**: 7/4/20

TEST PIT NO:

LOGGED BY:

**TP1513** 

1 OF 1

ВВ

		IENT TYPI IT LENGTI		2.7 TC 2.0 m		EXCA I <b>DTH</b> :	VATOR SURF 0.5 m DATU	FACE RL: JM:					
	Dril	ing and San	npling				Material description and profile information				Field	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticit characteristics,colour,minor componen	y/particle ts	MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
				-		sc	FILL-TOPSOIL: Clayey SAND - fine to med grained, grey-brown, fines of low plasticity, sticks and mulch.		М				FILL - TOPSOIL
				-		CI	6.20m FILL: Gravelly Sandy CLAY - medium plast orange-brown, fine to coarse grained (mos medium grained) sand, fine to coarse grain angular to sub-angular gravel.	tly fine to			HP	300	FILL - CONTROLLED
		0.50m		0. <u>5</u>			O.40m  Sandy CLAY - medium to high plasticity, participated orange-brown with some pale grey, fine to grained sand.	— — — — ale medium	—	VSt	HP	380	RESIDUAL SÕIL
ш	Encountered	U50 0.70m		-			Pale grey and red-brown to pale orange-br	own.			HP	410	
	Not			1. <u>0</u>		СН			M ~ W <sub>P</sub>	VSt - H	HP	500	
				1. <u>5</u>		 CI	1.70m	lasticity,	_				EXTREMELY WEATHERED ROCK / RESIDUAL SOIL
				2.0_ -			medium grained sand.  Hole Terminated at 1.80 m  Slow progress						
				-									
Wat	Wat (Da - Wat Wat ata Ch	er Level te and time si er Inflow er Outflow anges radational or ansitional stra	hown)	Notes, Sa U <sub>50</sub> CBR E ASS B Field Test	50mm Bulk s Enviro (Glass Acid s (Plast Bulk s	n Diamei ample fo nmenta s jar, sea Sulfate S ic bag, a Sample	er tube sample or CBR testing I sample aled and chilled on site) ioil Sample air expelled, chilled) on detector reading (ppm)	S S F F St S VSt \	/ery Soft Soft Firm Stiff /ery Stiff Hard Friable V L	V	25 50 10 20 20 20 ery Lo		D Dry M Moist W Wet W <sub>p</sub> Plastic Limit W <sub>L</sub> Liquid Limit  Density Index <15% Density Index 15 - 35%
QT LIB 1.1.GLB	tra D		ata		Photo Dynar	nic pene	on detector reading (ppm) etrometer test (test depth interval shown) meter test (UCS kPa)	<u>Bensity</u>		L( ) N D	oose	n Dense	Density Index 15 - 3



ENT: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD PAGE:

**PROJECT:** BILLYS LOOKOUT - STAGE 15 **JOB NO:** NEW15P-0070B

LOCATION: FISHERMANS DRIVE, TERALBA

**DATE**: 7/4/20

TEST PIT NO:

LOGGED BY:

TP1514

1 OF 1

ВВ

		IT LENGTH		2.0 m		IDTH:		JM:					
	Dril	ling and Samp	pling				Material description and profile information				Fiel	d Test	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity characteristics,colour,minor component		MOISTURE	CONSISTENCY DENSITY	Test Type	Result	Structure and additional observations
		0.20m U50 0.35m		- - - 0. <u>5</u>		CL	FILL-TOPSOIL: Sandy CLAY - low plasticity grey-brown, fine to coarse grained sand, wing sticks and mulch.  FILL: Gravelly Sandy CLAY - medium plast orange-brown, fine to coarse grained (most medium grained) sand, fine to coarse grain angular to sub-angular gravel.	ith some / / ticity, pale tly fine to	M ~ w ~ M	VSt - H	HP	450 530 500	FILL - TOPSOIL FILL - CONTROLLED
awing-lie>> 28.04/2020 19:56 10.0.000 Datget Lab and in Situ Tool	Not Encountered	0.95m		- 1. <u>0</u> - - - 1. <u>5</u>		СН	Sandy CLAY - medium to high plasticity, pa orange-brown and red-brown, fine to mediu grained sand.		M > W <sub>P</sub>	VSt	HP	350 330 350	RESIDUAL SOIL
Š.				- - 2.0_		CI	Orange-brown to red-brown and grey.  With some fine to medium grained sub-rou sub-angular gravel.  1.95m  Extremely Weathered Sandstone with soil poreaks down into Sandy CLAY - medium ploale grey and pale orange-brown, fine to congrained sand, with some fine to medium grangular to sub-angular gravel.  Hole Terminated at 2.05 m	properties; lasticity, parse	M < W <sub>P</sub>	Н	HP HP	500 450 >600	EXTREMELY WEATHERED ROCK
NON-CORED BOREHOL	✓ War (Da — War ✓ War — G — tr.	ter Level te and time sho ter Inflow ter Outflow	own)  F	Notes, Sal U <sub>50</sub> CBR E ASS B Field Test PID DCP(x-y) HP	50mm Bulk s Enviro (Glass Acid S (Plasti Bulk S S Photoi Dynan	Diame ample for menta sign, se Sulfate Sic bag, a sample sonisationic pendince pendi		S S F F St S VSt V H H	ery Soft oft irm tiff ery Stiff lard V L ME D VE	V L	25 50 10 20 >4 ery Lo	n Dense	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit W <sub>L</sub> Liquid Limit  Density Index <15% Density Index 15 - 35%



TEST PIT NO: MCCLOY DEVELOPMENT MANAGEMENT PTY LTD **PAGE**:

TP1515 1 OF 1

ВВ

PROJECT: BILLYS LOOKOUT - STAGE 15

JOB NO:

LOGGED BY:

NEW15P-0070B


LOCATION: FISHERMANS DRIVE, TERALBA

DATE: 7/4/20

WATER		ng  RL DEPTI (m)	GRA	© CLASSIFICATION O SYMBOL	Material description and profile information  MATERIAL DESCRIPTION: Soil type, plasticit characteristics, colour, minor componen  FILL-TOPSOIL: Clayey SAND / Sandy CL/coarse grained, grey-brown, fines of low plwith some sticks and mulch.  0.30m  FILL: Gravelly Sandy CLAY - low to medium plasticity, pale orange-brown, fine to coarse	AY - fine to asticity,	M - W CONDITION	CONSISTENCY DENSITY	Test Type	Result Result	Structure and additional observations  FILL - TOPSOIL
	0.40m U50	m) (m)	-	sc	characteristics,colour,minor componen  FILL-TOPSOIL: Clayey SAND / Sandy CL/ coarse grained, grey-brown, fines of low pli with some sticks and mulch.  0.30m  FILL: Gravelly Sandy CLAY - low to mediun plasticity, pale orange-brown, fine to coarse	AY - fine to asticity,		CONSISTENCY DENSITY	Test Type		observations
	U50	0.5			coarse grained, grey-brown, fines of low pl with some sticks and mulch.  0.30m  FILL: Gravelly Sandy CLAY - low to mediu plasticity, pale orange-brown, fine to coars	asticity, 	M - W				FILL - TOPSOIL
	U50	0.5		×	plasticity, pale orange-brown, fine to coarse	m					
Not Encountered		1.0		CL	(mostly fine to medium grained) sand, fine grained angular to sub-angular gravel.	e grained to coarse	M > w <sub>P</sub>	VSt	HP	300	FILL - CONTROLLED
		1.5		CI	to dark grey, fine to coarse grained sand, fi medium grained sub-rounded to sub-angul	ine to	M ~ W <sub>P</sub>	VSt - H	HP	400	RESIDUAL SÕIL
		2.0		СН	orange-brown, fine to medium grained san		M > W <sub>P</sub>	VSt	HP	380	RESIDUAL SUIL
(Dat Wat Wat a Cha Gi tra	te and time shown ter Inflow ter Outflow anges radational or ansitional strata	U <sub>50</sub> CBR E ASS B Field Te	50mm Bulk s Enviro (Glass Acid s (Plast Bulk s	n Diame sample f onmenta s jar, se Sulfate S ic bag, a Sample	ts ter tube sample or CBR testing al sample aled and chilled on site) soil Sample air expelled, chilled) on detector reading (ppm)	VS Ve S So F Fir St Sti VSt Ve H Ha	ery Soft off off off ery Stiff ord off off off off off off off off off of	Lo	<2 25 50 10 20 >4 ery Lo	25 5 - 50 0 - 100 00 - 200 00 - 400 000	D Dry M Moist W Wet W <sub>p</sub> Plastic Limit W <sub>L</sub> Liquid Limit  Density Index <15% Density Index 15 - 35%
	END: Wate	END: [ Water Level (Date and time show Water Inflow Water Outflow Inflow Changes Gradational or transitional strata	ND:  Water Level (Date and time shown) Water Outflow  Changes Gradational or transitional strata Definitive or distict  1.5  Notes, S. CBR E ASS  B Field Tes PID DCP(x-y) LD DCP(x-y) LD	2.0  ND:  Water Level (Date and time shown) Water Inflow Water Outflow Changes Gradational or transitional strata Definitive or distict  DEFINITION  Notes, Samples a U <sub>50</sub> 50mm CBR Bulk s E Envir (Glas ASS Acid s (Plast) Bulk s Field Tests PID Photo DCP(x-y) Dyna LBB Hand	TND:  Water Level (Date and time shown) Water Inflow Water Outflow  Changes  Gradational or transitional strata Definitive or distict  The stransition of transitional strata Definitive or distict  Total Cl  Action Samples and Test  U <sub>50</sub> 50mm Diame CBR Bulk sample E environmenta (Glass jar, se Acid Sulfate Sample Bulk Sample Field Tests  PID Photoionisation Dynamic penetral DCP(x-y) Dynamic penetral	IND:    CH   1.50m	FILL: Gravelly Sandy CLAY - medium plasticity, grey to dark grey, fine to coarse grained sand, fine to medium grained sub-rounded to sub-angular gravel.  1.5  CI  Sandy CLAY - medium to high plasticity, pale orange-brown, fine to medium grained sand.  CH  2.0  Hole Terminated at 2.05 m  Hole Terminated at 2.05 m  Water Level (Date and time shown) Water Inflow Water Inflow Water Inflow Water Inflow Water Outflow Inflow Inflowed Inflow Inflowed	ThD:    1.50m	Indicated the second of transitional strata content of dark grey fine to coarse grained sand, fine to medium grained sub-rounded to sub-angular gravel.  Indicated the sub-rounded the sub-rou	IND:    Common   Com	Indicate and time shown    Water Level   Cate and time shown    Cate and time shown    Water Inflow   Water Untflow   Changes     Changes   B Bulk sample     Changes   Changes     Changes

# **APPENDIX B:**

**Results of Laboratory Testing** 



02 4968 4468 02 4960 9775

E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



## **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

#### Report No: SSI:NEW20W-1322--S01 Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1322--S01

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1501 - (0.5 - 0.6m)

**Borehole Number:** TP1501 Borehole Depth (m): 0.5 - 0.6 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

#### AS 1289.7.1.1 Swell Test

Swell on Saturation (%): -1.3 Moisture Content before (%): 12.7 Moisture Content after (%): 16.5 Est. Unc. Comp. Strength before (kPa): >600 Est. Unc. Comp. Strength after (kPa):


#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 13.0 Est. inert material (%): 9 Crumbling during shrinkage: Nil Cracking during shrinkage: Moderate



Shrink Swell Index - Iss (%): 0.7

#### Comments



02 4968 4468 02 4960 9775

E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



## **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

#### Report No: SSI:NEW20W-1322--S02 Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1322--S02

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW

Sample Location: TP1502 - (0.95m - 1.10m)

**Borehole Number:** TP1502 Borehole Depth (m): 0.95 - 1.10 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

#### AS 1289.7.1.1 Swell Test

Swell on Saturation (%): -1.0 Moisture Content before (%): 12.7 Moisture Content after (%): 14.7 Est. Unc. Comp. Strength before (kPa): >600 Est. Unc. Comp. Strength after (kPa):


#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 13.0 Est. inert material (%): 20 Crumbling during shrinkage: NII Cracking during shrinkage: Minor



Shrink Swell Index - Iss (%): 0.2

#### Comments



02 4968 4468 02 4960 9775

E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



## **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

## Report No: SSI:NEW20W-1322--S03

Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1322--S03

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW

Sample Location: TP1503 - (0.35 - 0.6m)

**Borehole Number:** TP1503 Borehole Depth (m): 0.35 - 0.6 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

#### AS 1289.7.1.1 Swell Test

Swell on Saturation (%): -1.8 Moisture Content before (%): 13.0 Moisture Content after (%): 15.4 Est. Unc. Comp. Strength before (kPa): >600 Est. Unc. Comp. Strength after (kPa):


#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 13.0 Est. inert material (%): 5 Crumbling during shrinkage: Nil Cracking during shrinkage: Minor



Shrink Swell Index - Iss (%): 0.5

#### Comments



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1322--S05 Issue No: 1



Client Sample ID:

Sampling Method:

**Date Sampled:** 

**Date Submitted:** 

Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician)

NATA Accredited Laboratory Number: 18686 Date of Issue: 24/04/2020

Sampled by Engineering Department

Sample Details

Sample ID: NEW20W-1322--S05

Test Request No.:

Swell Test

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW

Sample Location: TP1505 - (0.5 - 0.65m)

**Borehole Number:** TP1505 **Borehole Depth (m): 0.5 - 0.65** 


> AS 1289.7.1.1 AS 1289.7.1.1 Shrink Test

7/04/2020


15/04/2020

Swell on Saturation (%): -1.2 Moisture Content before (%): 11.9 Moisture Content after (%): 19.9 Est. Unc. Comp. Strength before (kPa): 420 Est. Unc. Comp. Strength after (kPa):

Shrink on drying (%): Shrinkage Moisture Content (%): 13.3 Est. inert material (%): 10 Crumbling during shrinkage: NIL Cracking during shrinkage: Minor



Shrink Swell Index - Iss (%): 0.7



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1322--S06 Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician)

NATA Accredited Laboratory Number: 18686 Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1322--S06

Test Request No.:

Material: Sandy Clay Source: On Site Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1506 - (0.9 - 1.05m)

**Borehole Number:** TP1506 Borehole Depth (m): 0.9 - 1.05 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

## AS 1289.7.1.1 Swell Test


Swell on Saturation (%): -0.8 Moisture Content before (%): 26.6 Moisture Content after (%): 31.3 Est. Unc. Comp. Strength before (kPa): 570 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 27.6 Est. inert material (%): <1 Crumbling during shrinkage: NIL Cracking during shrinkage: NIL



# Shrink Swell Index - Iss (%): 2.4



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1322--S07 Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1322--S07

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW Sample Location:

TP1507 - (0.2 - 0.35m)

**Borehole Number:** TP1507 Borehole Depth (m): 0.2 - 0.35 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

## AS 1289.7.1.1 Swell Test


Swell on Saturation (%): -0.8 Moisture Content before (%): 15.9 Moisture Content after (%): 18.6 Est. Unc. Comp. Strength before (kPa): 470 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 16.6 Est. inert material (%): 5 Crumbling during shrinkage: Nil Cracking during shrinkage: Moderate



# Shrink Swell Index - Iss (%): 1.1



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1322--S08 Issue No: 1



Client Sample ID:

Sampling Method:

**Date Sampled:** 

**Date Submitted:** 

Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sampled by Engineering Department

Sample Details

Sample ID: NEW20W-1322--S08

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1508 - (0.2 - 0.35m)

**Borehole Number:** TP1508

Borehole Depth (m): 0.2 - 0.35


#### AS 1289.7.1.1 Shrink Test

7/04/2020


15/04/2020

Shrink on drying (%): Shrinkage Moisture Content (%): 12.8 Est. inert material (%): 15 Crumbling during shrinkage: Nil Cracking during shrinkage: Moderate

AS 1289.7.1.1 Swell Test Swell on Saturation (%): -1.1 Moisture Content before (%): 12.3 Moisture Content after (%): 26.5 Est. Unc. Comp. Strength before (kPa): 280 Est. Unc. Comp. Strength after (kPa):



Shrink Swell Index - Iss (%): 0.5



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1322--S04 Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen (Senior Geotechnician)

NATA Accredited Laboratory Number: 18686 Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1322--S04

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW

Sample Location: TP1509 - (0.3 - 0.50m)

**Borehole Number:** TP1509 Borehole Depth (m): 0.3 - 0.5 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

## AS 1289.7.1.1 Swell Test


Swell on Saturation (%): -0.2 Moisture Content before (%): 25.9 Moisture Content after (%): 30.8 Est. Unc. Comp. Strength before (kPa): 440 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 25.0 Est. inert material (%): <1 Crumbling during shrinkage: Nil Cracking during shrinkage: NIL



Shrink Swell Index - Iss (%): 2.3



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1324--S04

Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1324--S04

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1510 - (0.3 - 0.55m)

**Borehole Number:** TP1510 Borehole Depth (m): 0.3 - 0.55 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

#### AS 1289.7.1.1 Swell Test Swell on Saturation (%): -0.7


Moisture Content before (%): 26.5 Moisture Content after (%): 28.0 Est. Unc. Comp. Strength before (kPa): 38 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): 5.5 Shrinkage Moisture Content (%): 28.5 Est. inert material (%): 5 Crumbling during shrinkage: Nil Cracking during shrinkage: Nil



Shrink Swell Index - Iss (%): 3.1



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Sandy Clay

Principal:

Material:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1324--S01 Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 23/04/2020

Sample Details

Sample ID: NEW20W-1324--S01

Test Request No.:

Source: On Site Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1510 - (0.6 - 0.8m)

**Borehole Number:** TP1510 Borehole Depth (m): 0.6 - 0.8 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

#### AS 1289.7.1.1 Swell Test


Swell on Saturation (%): -1.0 Moisture Content before (%): 27.3 Moisture Content after (%): 30.2 Est. Unc. Comp. Strength before (kPa): 450 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 25.3 Est. inert material (%): 2 Crumbling during shrinkage: Nil Cracking during shrinkage: Minor



Shrink Swell Index - Iss (%): 3.0



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1324--S02 Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen (Senior Geotechnician)

NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1324--S02

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1512 - (0.6 - 0.8m)

**Borehole Number:** TP1512 Borehole Depth (m): 0.6 - 0.8 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

## AS 1289.7.1.1 Swell Test


Swell on Saturation (%): -0.7 Moisture Content before (%): 10.6 Moisture Content after (%): 22.9 Est. Unc. Comp. Strength before (kPa): >600 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): 1.1 Shrinkage Moisture Content (%): 13.0 Est. inert material (%): 10 Crumbling during shrinkage: Nil Cracking during shrinkage: Minor



Shrink Swell Index - Iss (%): 0.6



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Sandy Clay

Principal:

Material:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1324--S03 Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1324--S03

Test Request No.:

Source: On Site Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1513 - (0.5 - 0.7m)

**Borehole Number:** TP1513 Borehole Depth (m): 0.5 - 0.7 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

#### AS 1289.7.1.1 Swell Test


Swell on Saturation (%): -2.7 Moisture Content before (%): 17.0 Moisture Content after (%): 20.0 Est. Unc. Comp. Strength before (kPa): >600 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 19.0 Est. inert material (%): 12 Crumbling during shrinkage: Nil Cracking during shrinkage: Major



Shrink Swell Index - Iss (%): 1.6



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1324--S05

Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician)

NATA Accredited Laboratory Number: 18686 Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1324--S05

Test Request No.:

Material: Sandy Clay Source: On Site Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1514 - (0.5 - 0.95m)

**Borehole Number:** TP1514 Borehole Depth (m): 0.5 - 0.95 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

## AS 1289.7.1.1 Swell Test


Swell on Saturation (%): -1.3 Moisture Content before (%): 18.4 Moisture Content after (%): 23.1 Est. Unc. Comp. Strength before (kPa): >600 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): Shrinkage Moisture Content (%): 16.9 Est. inert material (%): 12 Crumbling during shrinkage: NII Cracking during shrinkage: Moderate



# Shrink Swell Index - Iss (%): 1.3



E: admin@qualtest.com.au W: www.qualtest.com.au ABN: 98 153 268 896



# **Shrink Swell Index Report**

Client: McCloy Development Management Pty Ltd

Suite 2, Ground Floor, 317 Hunter Street

Newcastle NSW 2300

Principal:

Project No.: NEW15P-0070B

Project Name: Billy's Lookout - Stage 15

# Report No: SSI:NEW20W-1324--S06

Issue No: 1



Accredited for compliance with ISO/IEC 17025-Testing.
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.
Results provided relate only to the items tested or sampled. This report shall not be reproduced except in full.

Approved Signatory: Dane Cullen

(Senior Geotechnician) NATA Accredited Laboratory Number: 18686

Date of Issue: 24/04/2020

Sample Details

Sample ID: NEW20W-1324--S06

Test Request No.:

Material: **Gravelly Sandy Clay** 

Source: On Site

Specification: No Specification **Project Location:** Teralba, NSW Sample Location: TP1515 - (0.4 - 0.55m)

**Borehole Number:** TP1515 Borehole Depth (m): 0.4 - 0.55 Client Sample ID:

Sampling Method: Sampled by Engineering Department


**Date Sampled:** 7/04/2020 **Date Submitted:** 15/04/2020

#### AS 1289.7.1.1 Swell Test

Swell on Saturation (%): -1.7 Moisture Content before (%): 17.0 Moisture Content after (%): 18.8 Est. Unc. Comp. Strength before (kPa): >600 Est. Unc. Comp. Strength after (kPa):

#### AS 1289.7.1.1 Shrink Test

Shrink on drying (%): 0.6 Shrinkage Moisture Content (%): 16.7 Est. inert material (%): 9 Crumbling during shrinkage: Nil Cracking during shrinkage: Minor



Shrink Swell Index - Iss (%): 0.4

# **APPENDIX C:**

**CSIRO Sheet BTF 18** 

Foundation Maintenance and Footing Performance: A Homeowner's Guide

# Foundation Maintenance and Footing Performance: A Homeowner's Guide



BTF 18 replaces Information Sheet 10/91

Buildings can and often do move. This movement can be up, down, lateral or rotational. The fundamental cause of movement in buildings can usually be related to one or more problems in the foundation soil. It is important for the homeowner to identify the soil type in order to ascertain the measures that should be put in place in order to ensure that problems in the foundation soil can be prevented, thus protecting against building movement.

This Building Technology File is designed to identify causes of soil-related building movement, and to suggest methods of prevention of resultant cracking in buildings.

# **Soil Types**

The types of soils usually present under the topsoil in land zoned for residential buildings can be split into two approximate groups – granular and clay. Quite often, foundation soil is a mixture of both types. The general problems associated with soils having granular content are usually caused by erosion. Clay soils are subject to saturation and swell/shrink problems.

Classifications for a given area can generally be obtained by application to the local authority, but these are sometimes unreliable and if there is doubt, a geotechnical report should be commissioned. As most buildings suffering movement problems are founded on clay soils, there is an emphasis on classification of soils according to the amount of swell and shrinkage they experience with variations of water content. The table below is Table 2.1 from AS 2870, the Residential Slab and Footing Code.

## **Causes of Movement**

## Settlement due to construction

There are two types of settlement that occur as a result of construction:

- Immediate settlement occurs when a building is first placed on its foundation soil, as a result of compaction of the soil under the weight of the structure. The cohesive quality of clay soil mitigates against this, but granular (particularly sandy) soil is susceptible.
- Consolidation settlement is a feature of clay soil and may take
  place because of the expulsion of moisture from the soil or because
  of the soil's lack of resistance to local compressive or shear stresses.
  This will usually take place during the first few months after
  construction, but has been known to take many years in
  exceptional cases.

These problems are the province of the builder and should be taken into consideration as part of the preparation of the site for construction. Building Technology File 19 (BTF 19) deals with these problems.

## **Erosion**

All soils are prone to erosion, but sandy soil is particularly susceptible to being washed away. Even clay with a sand component of say 10% or more can suffer from erosion.

## Saturation

This is particularly a problem in clay soils. Saturation creates a bog-like suspension of the soil that causes it to lose virtually all of its bearing capacity. To a lesser degree, sand is affected by saturation because saturated sand may undergo a reduction in volume – particularly imported sand fill for bedding and blinding layers. However, this usually occurs as immediate settlement and should normally be the province of the builder.

## Seasonal swelling and shrinkage of soil

All clays react to the presence of water by slowly absorbing it, making the soil increase in volume (see table below). The degree of increase varies considerably between different clays, as does the degree of decrease during the subsequent drying out caused by fair weather periods. Because of the low absorption and expulsion rate, this phenomenon will not usually be noticeable unless there are prolonged rainy or dry periods, usually of weeks or months, depending on the land and soil characteristics.

The swelling of soil creates an upward force on the footings of the building, and shrinkage creates subsidence that takes away the support needed by the footing to retain equilibrium.

## Shear failure

This phenomenon occurs when the foundation soil does not have sufficient strength to support the weight of the footing. There are two major post-construction causes:

- · Significant load increase.
- Reduction of lateral support of the soil under the footing due to erosion or excavation.
- In clay soil, shear failure can be caused by saturation of the soil adjacent to or under the footing.

GENERAL DEFINITIONS OF SITE CLASSES	
Class	Foundation
A	Most sand and rock sites with little or no ground movement from moisture changes
S	Slightly reactive clay sites with only slight ground movement from moisture changes
M	Moderately reactive clay or silt sites, which can experience moderate ground movement from moisture changes
Н	Highly reactive clay sites, which can experience high ground movement from moisture changes
Е	Extremely reactive sites, which can experience extreme ground movement from moisture changes
A to P	Filled sites
P	Sites which include soft soils, such as soft clay or silt or loose sands; landslip; mine subsidence; collapsing soils; soils subject to erosion; reactive sites subject to abnormal moisture conditions or sites which cannot be classified otherwise

Tree root growth

Trees and shrubs that are allowed to grow in the vicinity of footings can cause foundation soil movement in two ways:

- Roots that grow under footings may increase in cross-sectional size, exerting upward pressure on footings.
- Roots in the vicinity of footings will absorb much of the moisture in the foundation soil, causing shrinkage or subsidence.

## **Unevenness of Movement**

The types of ground movement described above usually occur unevenly throughout the building's foundation soil. Settlement due to construction tends to be uneven because of:

- Differing compaction of foundation soil prior to construction.
- Differing moisture content of foundation soil prior to construction.

Movement due to non-construction causes is usually more uneven still. Erosion can undermine a footing that traverses the flow or can create the conditions for shear failure by eroding soil adjacent to a footing that runs in the same direction as the flow.

Saturation of clay foundation soil may occur where subfloor walls create a dam that makes water pond. It can also occur wherever there is a source of water near footings in clay soil. This leads to a severe reduction in the strength of the soil which may create local shear failure.

Seasonal swelling and shrinkage of clay soil affects the perimeter of the building first, then gradually spreads to the interior. The swelling process will usually begin at the uphill extreme of the building, or on the weather side where the land is flat. Swelling gradually reaches the interior soil as absorption continues. Shrinkage usually begins where the sun's heat is greatest.

# **Effects of Uneven Soil Movement on Structures**

## **Erosion and saturation**

Erosion removes the support from under footings, tending to create subsidence of the part of the structure under which it occurs. Brickwork walls will resist the stress created by this removal of support by bridging the gap or cantilevering until the bricks or the mortar bedding fail. Older masonry has little resistance. Evidence of failure varies according to circumstances and symptoms may include:

- Step cracking in the mortar beds in the body of the wall or above/below openings such as doors or windows.
- Vertical cracking in the bricks (usually but not necessarily in line with the vertical beds or perpends).

Isolated piers affected by erosion or saturation of foundations will eventually lose contact with the bearers they support and may tilt or fall over. The floors that have lost this support will become bouncy, sometimes rattling ornaments etc.

Seasonal swelling/shrinkage in clay

Swelling foundation soil due to rainy periods first lifts the most exposed extremities of the footing system, then the remainder of the perimeter footings while gradually permeating inside the building footprint to lift internal footings. This swelling first tends to create a dish effect, because the external footings are pushed higher than the internal ones.

The first noticeable symptom may be that the floor appears slightly dished. This is often accompanied by some doors binding on the floor or the door head, together with some cracking of cornice mitres. In buildings with timber flooring supported by bearers and joists, the floor can be bouncy. Externally there may be visible dishing of the hip or ridge lines.

As the moisture absorption process completes its journey to the innermost areas of the building, the internal footings will rise. If the spread of moisture is roughly even, it may be that the symptoms will temporarily disappear, but it is more likely that swelling will be uneven, creating a difference rather than a disappearance in symptoms. In buildings with timber flooring supported by bearers and joists, the isolated piers will rise more easily than the strip footings or piers under walls, creating noticeable doming of flooring.



As the weather pattern changes and the soil begins to dry out, the external footings will be first affected, beginning with the locations where the sun's effect is strongest. This has the effect of lowering the external footings. The doming is accentuated and cracking reduces or disappears where it occurred because of dishing, but other cracks open up. The roof lines may become convex.

Doming and dishing are also affected by weather in other ways. In areas where warm, wet summers and cooler dry winters prevail, water migration tends to be toward the interior and doming will be accentuated, whereas where summers are dry and winters are cold and wet, migration tends to be toward the exterior and the underlying propensity is toward dishing.

## Movement caused by tree roots

In general, growing roots will exert an upward pressure on footings, whereas soil subject to drying because of tree or shrub roots will tend to remove support from under footings by inducing shrinkage.

## Complications caused by the structure itself

Most forces that the soil causes to be exerted on structures are vertical – i.e. either up or down. However, because these forces are seldom spread evenly around the footings, and because the building resists uneven movement because of its rigidity, forces are exerted from one part of the building to another. The net result of all these forces is usually rotational. This resultant force often complicates the diagnosis because the visible symptoms do not simply reflect the original cause. A common symptom is binding of doors on the vertical member of the frame.

## **Effects on full masonry structures**

Brickwork will resist cracking where it can. It will attempt to span areas that lose support because of subsided foundations or raised points. It is therefore usual to see cracking at weak points, such as openings for windows or doors.

In the event of construction settlement, cracking will usually remain unchanged after the process of settlement has ceased.

With local shear or erosion, cracking will usually continue to develop until the original cause has been remedied, or until the subsidence has completely neutralised the affected portion of footing and the structure has stabilised on other footings that remain effective.

In the case of swell/shrink effects, the brickwork will in some cases return to its original position after completion of a cycle, however it is more likely that the rotational effect will not be exactly reversed, and it is also usual that brickwork will settle in its new position and will resist the forces trying to return it to its original position. This means that in a case where swelling takes place after construction and cracking occurs, the cracking is likely to at least partly remain after the shrink segment of the cycle is complete. Thus, each time the cycle is repeated, the likelihood is that the cracking will become wider until the sections of brickwork become virtually independent.

With repeated cycles, once the cracking is established, if there is no other complication, it is normal for the incidence of cracking to stabilise, as the building has the articulation it needs to cope with the problem. This is by no means always the case, however, and monitoring of cracks in walls and floors should always be treated seriously.

Upheaval caused by growth of tree roots under footings is not a simple vertical shear stress. There is a tendency for the root to also exert lateral forces that attempt to separate sections of brickwork after initial cracking has occurred.

The normal structural arrangement is that the inner leaf of brickwork in the external walls and at least some of the internal walls (depending on the roof type) comprise the load-bearing structure on which any upper floors, ceilings and the roof are supported. In these cases, it is internally visible cracking that should be the main focus of attention, however there are a few examples of dwellings whose external leaf of masonry plays some supporting role, so this should be checked if there is any doubt. In any case, externally visible cracking is important as a guide to stresses on the structure generally, and it should also be remembered that the external walls must be capable of supporting themselves.

## Effects on framed structures

Timber or steel framed buildings are less likely to exhibit cracking due to swell/shrink than masonry buildings because of their flexibility. Also, the doming/dishing effects tend to be lower because of the lighter weight of walls. The main risks to framed buildings are encountered because of the isolated pier footings used under walls. Where erosion or saturation cause a footing to fall away, this can double the span which a wall must bridge. This additional stress can create cracking in wall linings, particularly where there is a weak point in the structure caused by a door or window opening. It is, however, unlikely that framed structures will be so stressed as to suffer serious damage without first exhibiting some or all of the above symptoms for a considerable period. The same warning period should apply in the case of upheaval. It should be noted, however, that where framed buildings are supported by strip footings there is only one leaf of brickwork and therefore the externally visible walls are the supporting structure for the building. In this case, the subfloor masonry walls can be expected to behave as full brickwork walls.

## Effects on brick veneer structures

Because the load-bearing structure of a brick veneer building is the frame that makes up the interior leaf of the external walls plus perhaps the internal walls, depending on the type of roof, the building can be expected to behave as a framed structure, except that the external masonry will behave in a similar way to the external leaf of a full masonry structure.

## Water Service and Drainage

Where a water service pipe, a sewer or stormwater drainage pipe is in the vicinity of a building, a water leak can cause erosion, swelling or saturation of susceptible soil. Even a minuscule leak can be enough to saturate a clay foundation. A leaking tap near a building can have the same effect. In addition, trenches containing pipes can become watercourses even though backfilled, particularly where broken rubble is used as fill. Water that runs along these trenches can be responsible for serious erosion, interstrata seepage into subfloor areas and saturation.

Pipe leakage and trench water flows also encourage tree and shrub roots to the source of water, complicating and exacerbating the problem.

Poor roof plumbing can result in large volumes of rainwater being concentrated in a small area of soil:

 Incorrect falls in roof guttering may result in overflows, as may gutters blocked with leaves etc.

- Corroded guttering or downpipes can spill water to ground.
- Downpipes not positively connected to a proper stormwater collection system will direct a concentration of water to soil that is directly adjacent to footings, sometimes causing large-scale problems such as erosion, saturation and migration of water under the building.

# Seriousness of Cracking

In general, most cracking found in masonry walls is a cosmetic nuisance only and can be kept in repair or even ignored. The table below is a reproduction of Table C1 of AS 2870.

AS 2870 also publishes figures relating to cracking in concrete floors, however because wall cracking will usually reach the critical point significantly earlier than cracking in slabs, this table is not reproduced here.

## Prevention/Cure

## Plumbing

Where building movement is caused by water service, roof plumbing, sewer or stormwater failure, the remedy is to repair the problem. It is prudent, however, to consider also rerouting pipes away from the building where possible, and relocating taps to positions where any leakage will not direct water to the building vicinity. Even where gully traps are present, there is sometimes sufficient spill to create erosion or saturation, particularly in modern installations using smaller diameter PVC fixtures. Indeed, some gully traps are not situated directly under the taps that are installed to charge them, with the result that water from the tap may enter the backfilled trench that houses the sewer piping. If the trench has been poorly backfilled, the water will either pond or flow along the bottom of the trench. As these trenches usually run alongside the footings and can be at a similar depth, it is not hard to see how any water that is thus directed into a trench can easily affect the foundation's ability to support footings or even gain entry to the subfloor area.

## Ground drainage

In all soils there is the capacity for water to travel on the surface and below it. Surface water flows can be established by inspection during and after heavy or prolonged rain. If necessary, a grated drain system connected to the stormwater collection system is usually an easy solution.


It is, however, sometimes necessary when attempting to prevent water migration that testing be carried out to establish watertable height and subsoil water flows. This subject is referred to in BTF 19 and may properly be regarded as an area for an expert consultant.

# Protection of the building perimeter

It is essential to remember that the soil that affects footings extends well beyond the actual building line. Watering of garden plants, shrubs and trees causes some of the most serious water problems.

For this reason, particularly where problems exist or are likely to occur, it is recommended that an apron of paving be installed around as much of the building perimeter as necessary. This paving

## CLASSIFICATION OF DAMAGE WITH REFERENCE TO WALLS Description of typical damage and required repair Approximate crack width **Damage** limit (see Note 3) category Hairline cracks < 0.1 mm 0 Fine cracks which do not need repair 1 <1 mm 2 Cracks noticeable but easily filled. Doors and windows stick slightly <5 mm 3 Cracks can be repaired and possibly a small amount of wall will need 5-15 mm (or a number of cracks to be replaced. Doors and windows stick. Service pipes can fracture. 3 mm or more in one group) Weathertightness often impaired Extensive repair work involving breaking-out and replacing sections of walls, 15-25 mm but also depend 4 especially over doors and windows. Window and door frames distort. Walls lean on number of cracks or bulge noticeably, some loss of bearing in beams. Service pipes disrupted



should extend outwards a minimum of 900 mm (more in highly reactive soil) and should have a minimum fall away from the building of 1:60. The finished paving should be no less than 100 mm below brick vent bases.

It is prudent to relocate drainage pipes away from this paving, if possible, to avoid complications from future leakage. If this is not practical, earthenware pipes should be replaced by PVC and backfilling should be of the same soil type as the surrounding soil and compacted to the same density.

Except in areas where freezing of water is an issue, it is wise to remove taps in the building area and relocate them well away from the building – preferably not uphill from it (see BTF 19).

It may be desirable to install a grated drain at the outside edge of the paving on the uphill side of the building. If subsoil drainage is needed this can be installed under the surface drain.

# Condensation

In buildings with a subfloor void such as where bearers and joists support flooring, insufficient ventilation creates ideal conditions for condensation, particularly where there is little clearance between the floor and the ground. Condensation adds to the moisture already present in the subfloor and significantly slows the process of drying out. Installation of an adequate subfloor ventilation system, either natural or mechanical, is desirable.

*Warning*: Although this Building Technology File deals with cracking in buildings, it should be said that subfloor moisture can result in the development of other problems, notably:

- Water that is transmitted into masonry, metal or timber building elements causes damage and/or decay to those elements.
- High subfloor humidity and moisture content create an ideal environment for various pests, including termites and spiders.
- Where high moisture levels are transmitted to the flooring and walls, an increase in the dust mite count can ensue within the living areas. Dust mites, as well as dampness in general, can be a health hazard to inhabitants, particularly those who are abnormally susceptible to respiratory ailments.

The garden

The ideal vegetation layout is to have lawn or plants that require only light watering immediately adjacent to the drainage or paving edge, then more demanding plants, shrubs and trees spread out in that order

Overwatering due to misuse of automatic watering systems is a common cause of saturation and water migration under footings. If it is necessary to use these systems, it is important to remove garden beds to a completely safe distance from buildings.

**Existing trees** 

Where a tree is causing a problem of soil drying or there is the existence or threat of upheaval of footings, if the offending roots are subsidiary and their removal will not significantly damage the tree, they should be severed and a concrete or metal barrier placed vertically in the soil to prevent future root growth in the direction of the building. If it is not possible to remove the relevant roots without damage to the tree, an application to remove the tree should be made to the local authority. A prudent plan is to transplant likely offenders before they become a problem.

## Information on trees, plants and shrubs

State departments overseeing agriculture can give information regarding root patterns, volume of water needed and safe distance from buildings of most species. Botanic gardens are also sources of information. For information on plant roots and drains, see Building Technology File 17.

## Excavation

Excavation around footings must be properly engineered. Soil supporting footings can only be safely excavated at an angle that allows the soil under the footing to remain stable. This angle is called the angle of repose (or friction) and varies significantly between soil types and conditions. Removal of soil within the angle of repose will cause subsidence.

## Remediation

Where erosion has occurred that has washed away soil adjacent to footings, soil of the same classification should be introduced and compacted to the same density. Where footings have been undermined, augmentation or other specialist work may be required. Remediation of footings and foundations is generally the realm of a specialist consultant.

Where isolated footings rise and fall because of swell/shrink effect, the homeowner may be tempted to alleviate floor bounce by filling the gap that has appeared between the bearer and the pier with blocking. The danger here is that when the next swell segment of the cycle occurs, the extra blocking will push the floor up into an accentuated dome and may also cause local shear failure in the soil. If it is necessary to use blocking, it should be by a pair of fine wedges and monitoring should be carried out fortnightly.

This BTF was prepared by John Lewer FAIB, MIAMA, Partner, Construction Diagnosis.

The information in this and other issues in the series was derived from various sources and was believed to be correct when published.

The information is advisory. It is provided in good faith and not claimed to be an exhaustive treatment of the relevant subject.

Further professional advice needs to be obtained before taking any action based on the information provided.

Distributed by

CSIRO PUBLISHING PO Box 1139, Collingwood 3066, Australia

Freecall 1800 645 051 Tel (03) 9662 7666 Fax (03) 9662 7555 www.publish.csiro.au

Email: publishing.sales@csiro.au

© CSIRO 2003. Unauthorised copying of this Building Technology file is prohibited